

UltraBand[™] Version 6.2.10

Release Notes

Copyright

Copyright 2009-2019© by PeerApp 401 Congress Avenue, Suite 2650, Austin, TX 78701, USA. info@peerapp.com www.peerapp.com support@zephyrtel.com

Table of Contents

| Release Overview | 3 |
|--------------------------------|---|
| Fixed Customer Defects Summary | 3 |
| Fault Analysis Report | 3 |
| IPv6 ICMP echo failure | 3 |

Release Overview

| Release Version | UltraBand 6.2.10 | | |
|------------------------|--|--|--|
| Release Date | December 10, 2019 | | |
| Release Type | General Availability | | |
| Deliverables | ISO image for fresh installations of UltraBand 6.2.10 Release Documentation (Release Notes) | | |
| Additional Information | Improvements since UltraBand 6.2.8 release: 1 customer defect | | |

Fixed Customer Defects Summary

| JIRA ID | Zendesk ID | Description |
|------------|------------|------------------------|
| PAUB-25188 | #2023828 | IPv6 ICMP echo failure |

Fault Analysis Report

IPv6 ICMP echo failure

It was found that ICMP on Bounce Mode under some circumstances was not allowing ICMP to do echo requests into data interfaces. After doing a deep low-level analysis, it was found that an unconventional situation caused IPv6 checksums to corrupt, causing data transmission drops that resulted in the error. It has been now fixed.